ECS Configuration Change Request					TPage 1 of	Pag	ge(s)
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:	6. Rm #:	7. Dept.
Tim Wells	7-20-00	00-67	149		883-4021	1075	ILS/M&O
8. CCR Title: Updated NSIDC Cable Management Plan and NSIDC Floor Plan							
1 - •			10. Cl	ass	11. Type: 12. Need Date: 07/25/00		
Temothy & Wells 7-19-00			\square	// CCR			
				4. Category of Change: Jpdate ECS Baseline Doc. 15. Priority: (If "Emergency" fill in Block 28). Routine			
16. Documentation/Drawing			7. Sched	lule	18. Cl(s) Ai	fected:none	 -
920-TDN-005	•	I .	mpact:				
920-TDN-004 none 19. Release Affected by this Change: 20. Date due to Customer: 21. Estimated Cost:							
5A 07/25/00				None - Under 100K			
22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☒Other: 920-TDN-005 Rev 3, 920-TDN-004							
23. Problem: (use additional Sheets if necessary) NSIDC cable management plan has changed in order to ready the DAAC for connectivity to the gigabyte ethernet switch. The floor plan changed due to the addition of n0icg01.							
24. Proposed Solution: (use additional sheets if necessary) Update the baseline documents to reflect the cable and floor plan changes changes.							
25. Alternate Solution: (use additional sheets if necessary) none							
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Outdated cable management and floor plans for NSIDC							
27. Justification for Emergency (If Block 15 is "Emergency"): N/A							
28. Site(s) Affected: E		EDC [GSFC [∐LaRC	⊠NSIDC □	ISMC □AK [JPL
29. Board Comments:				30. W	ork Assigned To	o: 31. CCR C	losed Date:
32. EDF/SCDV CCB Chair (S	Sign/Date): Disp	•	proved .	App/Con	m. Disapproved	Withdraw Fwo	/ESDIS ERB
33. M&O CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS EF							VESDIS ERB
w 2 The od Fwd/ECS							
34. ECS CCB Chair (Sign/D		sition: App	roved A	pp/Com	. Disapproved	Withdraw Fw	d/ESDIS ERB

CM01JA00

Fwd/ESDIS

ORIGINAL CONTROL OF THE PROPERTY OF THE PROPER